

# E8F2

## Pressure Sensor with Easy-to-Read LED Display

- Pressure status can be checked at a glance from the red digital pressure value and analog bar displays.
- Measurement pressure is averaged by the chattering prevention function to prevent incorrect outputs due to momentary pressure changes.
- The automatic teaching function teaches pressure values for good and bad products.
- Industry's smallest models at just 28 × 28 × 29 mm.





 Be sure to read *Safety Precautions* on page 6.

## Ordering Information

### Sensors

Pressure range		ON/OFF output	Linear output	Model	
				NPN output	PNP output
Positive pressure	0 to 100 kPa	Open collector (two independent outputs)	1 to 5 V	<b>E8F2-A01C</b>	<b>E8F2-A01B</b>
	0 to 1 MPa			<b>E8F2-B10C</b>	<b>E8F2-B10B</b>
Negative pressure	0 to -101 kPa			<b>E8F2-AN0C</b>	<b>E8F2-AN0B</b>

### Accessories (Order Separately)

Appearance	Name	Model	Remarks
	Mounting Bracket	<b>E89-F3</b>	Provided with the E8F2.
	Panel-mounting Bracket	<b>E89-F4</b>	Spacer provided.

## Ratings and Specifications

### Sensor

Item	Model	NPN output PNP output	E8F2-A01C		E8F2-B10C		E8F2-AN0C	
			E8F2-A01B		E8F2-B10B		E8F2-AN0B	
Power supply voltage	12 to 24 VDC±10% with a ripple (p-p) of 10% max.							
Current consumption	70 mA max. *1							
Pressure type	Gauge pressure							
Rated pressure range	0 to 100 kPa		0 to 1 MPa		0 to -101 kPa			
Pressure setting range	0 to 100 kPa		0 to 1 MPa		0 to -101 kPa			
Withstand pressure	400 kPa		1.5 MPa		400 kPa			
Applicable fluid	Non-corrosive gas and non-flammable gas							
Operating mode	Hysteresis mode, window mode, and automatic teaching mode							
Repeat accuracy (ON/OFF output)	±1%FS max.							
Linearity (linear output)	±1%FS max.							
Response time (ON/OFF output)	5 ms max.							
Linear output	1 to 5 V with an output impedance of 1 kΩ and a permissible resistive load of 500 kΩ.							
ON/OFF outputs	NO or NC open collector (depending on whether the output configuration is NPN or PNP)							
	Load current	30 mA max.						
	Output applied voltage	30 VDC max.						
	Residual voltage	NPN open collector output: 1 V max. with 30 mA load current PNP open collector output: 2 V max. with 30 mA load current						
Display *2	3.5-digit red LED Green LED bar indicator The orange LED is lit for two independent outputs with output transistor turned ON. Green unit indicator							
Display accuracy	±3%FS±1 digit max.							
Protection circuits	Reverse polarity protection, load short-circuit protection							
Ambient temperature range	Operating: 0 to 55°C Storage: -10 to 60°C (with no icing)							
Ambient humidity range	Operating/Storage: 35% to 85% (with no condensation)							
Temperature influence	±3%FS max.							
Voltage influence	±1.5%FS max.							
Insulation resistance	100 MΩ min. (at 500 VDC) between current-carrying parts and case							
Dielectric strength	1,000 VAC at 1 min							
Vibration resistance	Destruction: 10 to 500 Hz, 1.0-mm double amplitude or 150 m/s <sup>2</sup> , three times each for 11 min in the X, Y, and Z directions							
Shock resistance	Destruction: 300 m/s <sup>2</sup> 3 times each in the X, Y, and Z directions							
Degree of protection	IP50 (IEC)							
Pressure port	R (PT) 1/8 taper screw and M5 female screw							
Connection method	Pre-wired (standard length: 2 m)							
Cable	Approved by UL							
Weight (packed state)	Approx. 110 g							
Material	Pressure port	Aluminum die-cast						
	Case	Heat-resistive ABS						
Accessories	Mounting Bracket, Instruction manual							

\*1. The current consumption is approximately 43 mA in energy-saving mode.

\*2. Display Example of Digital Indicator


Model	Setting unit				
	kPa				
	Applied pressure	Digital display			
E8F2-A01C	100	1	0	0	0 ● 0
E8F2-B10C	1000	1	0	0	0
E8F2-AN0C	-101	-1	0	1	0 ● 0

Note: The period (●) in the display indicates the decimal point.  
Its position will not change unless the setting unit is changed.


## Engineering Data (Typical)

### Temperature vs. Linear Output Current Fluctuation    Temperature vs. Operating Pressure Fluctuation

E8F2-A01 □




E8F2-A01 □




### Pressure vs. Linear Output

E8F2-A01 □



### Linearity

E8F2-A01 □



# I/O Circuit Diagrams


## NPN Output

Operating mode	Model	Timing chart		Output circuit
		Hysteresis mode	Window mode	
NO	E8F2-A01C E8F2-B10C E8F2-AN0C			

## PNP Output

Operating mode	Model	Timing chart		Output circuit
		Hysteresis mode	Window mode	
NO	E8F2-A01B E8F2-B10B E8F2-AN0B			




## Nomenclature



### Display Panel

- (1) Bar Indicator (Green)**  
Indicates the degree of measured pressure in relation to the set pressure.
- (2) Numeric and Menu Display (Red)**  
Indicates measurement values and setting menu items.
- (3) Unit indicator (Green)**  
Indicates the unit used for detection. The unit indicated on the indicator is the one currently set.
- (4) OUT1 Indicator (Orange)**  
Lit when OUT1 is turned ON.
- (5) OUT2 Indicator (Orange)**  
Lit when OUT2 is turned ON.

### Operation Keys

- (6)  Up Key, (7)  Down Key**
  - Used to select or change the set items, set contents, and set values in setting mode.
  - Press either key to check the ON and OFF points in measurement mode. The values are reset by pressing both keys simultaneously.
  - Use together with the SET Key for setting the Sensor to a special setting mode or energy-saving mode.
- (7)  SET Key**
  - Used for entering the set contents and set values in setting mode.
  - Used for setting the Sensor to basic setting mode or pressure setting mode.

## Safety Precautions

Refer to *Warranty and Limitations of Liability*.

### WARNING

This product is not designed or rated for ensuring safety of persons either directly or indirectly. Do not use it for such purposes.



### Precautions for Correct Use

Do not use this product in atmospheres or environments that exceed product ratings.

#### ● Installation


Do not use the Sensor in an environment subject to corrosive or combustible gas.

#### ● Wiring

If no linear output is used, cut the gray lead wire short and apply insulating tape to the lead wire so that it will not come into contact with any other terminal.

#### ● Mounting

- Do not apply a tensile strength in excess of 50 N to the cables or connectors.
- The pressure port (made of aluminum die-cast) is fixed with tapered R(PT) 1/8 male screws and M5 female screws. When using tapered screws, use tapered Rc(PT) 1/8 female screws.
- Wrap the tapered R(PT) 1/8 male screws with sealing tape to prevent any leakage. Tighten the male screws to a torque of 10 N·m max.
- Tighten M5 female screws to a torque of 2 N·m max.
- Tighten each male screw by using a 12-mm wrench to hold its hexagonal head, not its body.



- When attaching the Mounting Bracket to the Sensor, make sure that each M3 screw is tightened to a torque of 0.5 N·m max.

#### ● Adjustments

- Filter the gas with an appropriate air filter so that the applied gas will be free of moisture or oil.
- Be sure to use the Sensor under the rated pressure.
- When setting the set pressure of the ON or OFF point of the output transistor by pressing the mode selection key, use a manometer if precise pressure settings are required. The Sensor has a display error of  $\pm 3\%$  FS  $\pm 1$  digit at room temperature. Refer to *Display accuracy in Ratings and Specifications*.
- Turning ON the power  
The Sensor is ready to operate 0.5 s after it is turned ON. When the load and Sensor are connected to separate power supplies, be sure to turn ON the Sensor first.





#### ● Others

Make sure the Sensor does not get wet.

Dimensions


Sensors

E8F2







4-dia. vinyl-insulated round cable with 5 conductors  
(Conductor cross-section: 0.15 mm<sup>2</sup>, Insulator diameter: 0.9 mm),  
Standard length: 2 m

With Mounting Bracket Attached




Mounting Hole Dimensions




Accessories

Mounting Bracket


E89-F3




Note: Provided with the E8F2.



**Panel-mounting Bracket**  
E89-F4



Note: Spacer provided.



\* Applicable panel thickness: 1.2 to 4 mm

Note: The spacer can be removed from the Panel-mounting Bracket. The panel cutout dimensions can be adjusted as shown above by attaching or detaching the spacer.



## E8F2

### Reading the Digital Display

The E8F2 displays alphanumeric characters, such as measurement values and menu items, on a 7-segment display. Examples are shown below.

Display	Meaning
oPE	Output type: Operation
kPa	Unit: kPa
Ud	Width


The following abbreviations are used by the digital display.

Abbreviation	Meaning	Abbreviation	Meaning
Unt	Unit	DSP	Display
M-A	Manual/Auto	AVE	Average
OPE	Operation	BAR	Bar
PRT	Protect	AUT	Auto
HYS	Hysteresis	ECO	Echo
WID	Width		

A	b	c	d	E	F	G	H	i	J	K	L	M	N	o	P	Q	R	S	T	U	V	W	X	Y	Z
A	B	C	D	E	F	G	H	I	J	K	L	M	N	O	P	Q	R	S	T	U	V	W	X	Y	Z

### Modes

The E8F2 has a variety of functions in addition to a measurement value display function. These functions are divided in four modes, with the measurement mode branching into three subordinate modes. The relationship among each mode and switching methods is shown in the following figure.



Note 1.  $\downarrow$  means to press a key for approximately two seconds. ( $\downarrow$  means to press for three seconds.)

2. The following conditions exist when returning from a setting mode to the measurement mode.

$\downarrow$ : The setting value is saved.


$\uparrow$  +  $\downarrow$ : The setting value is not saved. (Previous setting remains.)

\*1. Moves when the pressure setting method in the initial setting mode is set to  $\bar{n}$  (manual).

\*2. Moves when the pressure setting method in the initial setting mode is set to  $\bar{A}$  (auto teaching).

### Zero Reset


Note: Perform the zero reset with the Sensor open to atmospheric pressure.



Press  $\uparrow$  and  $\downarrow$  at the same time to reset the displayed measurement value to zero. The zero reset must be within  $\pm 5\%$  FS of the rated pressure. If this range is exceeded, the zero reset will be invalid.


### Initial Setting Mode

Set the unit, pressure setting method, and output type in the initial setting mode.



1. When  $\text{SET}$  is pressed for approx. 2 s, the system will enter initial setting mode, and the setting item *Unit* will be displayed.
2. Select the setting items (*Unit*, *n-R*, *oPE*), using  $\uparrow$  and  $\downarrow$ .

### Unit Setting (Reference)




1. Press  $\text{SET}$  when *Unit* is displayed, and the set unit will be displayed.
2. Select the unit using  $\uparrow$  and  $\downarrow$ .
3. Press  $\text{SET}$  to select the displayed unit, and the system will return to the setting item display (*Unit*).
4. Press  $\uparrow$  and  $\downarrow$  at the same time to return to the setting item display (*Unit*) without changing the selection.

Note: The unit mmHg can be set only with the E8F2-AN0□.

**Note: This menu item is prohibited in Japan due to revisions to the Measurement Law that prohibit the use of non-SI units. Leave the setting at the initial setting of *kPa* (kPa) and do not change the setting to other units.**


Pressure Setting Method



$\bar{n}$  : Manual setting (The ON point and OFF point are set manually.)  
 $\bar{A}$  : Auto teaching (The ON point and OFF point are automatically set to match the actual object.)

1. Press SET when  $\bar{n}-\bar{A}$  is displayed, and the set pressure setting method will be displayed.
2. Select the pressure setting method using  $\leftarrow$  and  $\rightarrow$ .
3. Press SET to select the displayed pressure setting method, and the system will return to the setting item display ( $\bar{n}-\bar{A}$ ).
4. Press  $\leftarrow$  and  $\rightarrow$  at the same time to return to the setting item display  $\bar{n}-\bar{A}$  without changing the selection.


Output Type Setting



$\bar{nO}$  : Normally open  
 $\bar{nL}$  : Normally closed

1. Press SET when  $\bar{OPE}$  is displayed, and the set output type for OUT1 will be displayed.
2. Select the output type using  $\leftarrow$  and  $\rightarrow$ .
3. Press SET to select the displayed output type, and the set output type for OUT2 will be displayed.
4. Select the output type using  $\leftarrow$  and  $\rightarrow$ .
5. Press SET to select the displayed output type for OUT2, and the system will return to the setting item display ( $\bar{OPE}$ ).
6. Press  $\leftarrow$  and  $\rightarrow$  at the same time to return to the setting item display ( $\bar{OPE}$ ) without changing the selection.

Returning to Measurement Mode



To save the setting:

Press the SET for approx. 2 s when the setting item is displayed.

To not save the setting:

Press  $\leftarrow$  and  $\rightarrow$  at the same time when the setting item is displayed.

### Pressure Setting Mode

The E8F2 outputs signals based on the measurement values and can be used to control external devices, such as valves and vacuum equipment.

To control external devices, a reference value is set, and settings are made so that the output turns ON if the measurement value exceeds the reference value, and OFF if it falls below the reference value. (This relationship can also be reversed.)

Pressure setting mode is used to set the point at which output

turns ON (ON point) and the point at which output turns OFF (the OFF point). There are two setting methods: manual and auto-teaching.


This section describes these setting methods for the ON points and OFF points. (Note: The following description applies when the output type is set to normally open.) Also, the hysteresis mode and window mode are determined by the relation between the ON point and the OFF point. (Refer to the following table for details.)

Mode	Relation between ON/OFF set values	Operating mode	
		Normally open	Normally closed
Hysteresis mode	ON-point set value > OFF-point set value		
Window mode	ON-point set value < OFF-point set value		
ON-point set value = OFF-point set value		The output will be unstable. Use hysteresis mode or window mode.	

Note: Standard default settings: ON point = (-)30 kPa, OFF point = (-)27 kPa. Negative values are for the E8F2-AN0C only.

### Manual Setting

Note: Manual setting can be performed if  $\bar{n}$  is selected for the pressure setting method in the initial settings.



1. Press  $\odot$  to enter the pressure setting mode, and  $\bar{ON}$  and the set ON point for OUT1 will be alternately displayed.
2. Change the ON point (for OUT1) using  $\odot$  and  $\ominus$ .
3. Press  $\odot$  to select the displayed ON point, and  $\bar{OFF}$  and the set OFF point for OUT1 will be alternately displayed.
4. Change the OFF point (for OUT1) using  $\odot$  and  $\ominus$ .
5. Press  $\odot$  to select the displayed OFF point, and  $\bar{ON}$  and the set ON point for OUT2 will be alternately displayed.
6. Change the ON point (for OUT2) using  $\odot$  and  $\ominus$ .
7. Press  $\odot$  to select the displayed ON point, and  $\bar{OFF}$  and the set OFF point for OUT2 will be alternately displayed.
8. Change the OFF point (for OUT2) using  $\odot$  and  $\ominus$ .
9. Press  $\odot$  to select the displayed OFF point, and  $\bar{ON}$  and the set ON point for OUT1 will be alternately displayed.

#### Returning to Measurement Mode

**Saving the set value**.....Press  $\odot$  for approx. 2 s. (Valid for any set value display.)


**Not saving the set value**.....Press  $\odot$  and  $\ominus$  at the same time. (Valid for any set value display.)

**Auto Teaching**



By using auto teaching, measurement values can be input as set values for the ON point and OFF point rather than by using key entry. There are two types of teaching: one-point teaching to set one point and two-point teaching to set two points.

Note: Auto-teaching can be performed if  $\bar{H}$  is selected for the pressure setting method in the initial settings.


**One-point Teaching**



**Two-point Teaching**




1. Press (SET) to enter pressure setting mode. The OUT1 indicator light and the L.H.1 will be displayed.
2. Select one-point teaching or two-point teaching for OUT1 or OUT2 using (⊙) and (⊘).




L.H.1: Teaching, hysteresis mode, first point  
L.U : Teaching, window mode

**• Two-point Teaching (Hysteresis Mode Teaching) OUT1**




1. Press (SET) at condition 1 in the following figure when L.H.1 is displayed, and the present measurement value will be displayed.
2. Check the measurement value, and press (SET). Teaching for the first point will be completed when teaching is executed.
3. Press (SET) at condition 2 in the following figure to display the present measurement value.

**Two-point Teaching**



There will be no problem if the order or size of TEACH 1 and TEACH 2 are reversed.

ON point = (TEACH1 + TEACH2) ÷ 2  
OFF point = ON point - 3% FS  
Default: 3% FS (Can be changed.)



4. Check the measurement value, and press (SET). Teaching for the second point will be completed when teaching is executed.
5. Press (SET) for approx. 2 s when L.H.1 is displayed, the set value will be set using teaching, and the system will return to measurement mode.
6. Press (⊙) and (⊘) at the same time to return to measurement mode without changing the selection.



Note: Hysteresis mode will be set automatically if 2-point teaching is performed.

This function is convenient for applications for checking a vacuum pressure.

**Auto Teaching**


**• One-point Teaching (Window Mode Teaching)**

**OUT1**



1. Press **SET** at condition 3 in the following figure when  $L.U$  is displayed, and the present measurement value will be displayed.

**One-point Teaching**




2. Check the measurement value and press **SET**. Teaching will be completed when teaching is executed.
3. Press **SET** for approx. 2 s when  $L.U$  is displayed. The set value will be set using teaching, and the system will return to measurement mode.
4. Press **←** and **→** at the same time to return to measurement mode without changing the selection.

Note: Window mode will be set automatically if 1-point teaching is performed.

This function is convenient for applications to confirm source pressure.

**• Teaching Errors**

The current value is out of the setting range.




Error is displayed for 1 s.

Meaning of display: Er.t (error teaching)


- Pressing **SET** will not be enabled if the present value is outside the setting range or the calculation result after teaching is outside the setting range. In that case, an error message will be displayed for 1 s if teaching is executed.

### Special Setting Mode

Set the key protection, hysteresis width, window width, display refresh speed, measurement averaging times, and bar display range in special setting mode.



### Key Protect Setting




1. Press **SET** when *Prt* is displayed, and the set key protect set value will be displayed.
2. Change the set value using **↶** and **↷**.
3. Press **SET** to select the displayed set value, and the system will return to the setting item display (*Prt*).
4. Press **↶** and **↷** at the same time to return to the setting item display (*Prt*) without changing the selection.

### Key Protection Status


- 0: No key protection will be set.
- 1: Initial setting and pressure setting will be prohibited.
- 2: Moving to any function other than pressure setting confirmation, special settings, and the energy saving function will be prohibited.

### Hysteresis Width Setting


The hysteresis width can be changed as shown in the following figure. (The hysteresis mode, however, can be changed only if it is set using teaching.)



### Hysteresis mode



### Window mode



1. Press **SET** when *HYS* is displayed, and the hysteresis width set value set for OUT1 will be displayed.
2. Change the set value using **↶** and **↷**. The setting range is 0% to 10% FS.
3. Press **SET** to select the displayed set value, and the hysteresis width set value set for OUT2 will be displayed.
4. Change the set value using **↶** and **↷**.
5. Press **SET** to select the displayed set value, and the system will return to the setting item display (*HYS*).
6. Press **↶** and **↷** at the same time to return to the setting item display (*HYS*) without changing the selection.

#### Note 1. Hysteresis Mode



The hysteresis width setting is not valid if the set values were set manually. It is valid only if auto-teaching was used.

#### Window Mode

The hysteresis width setting is valid for the measurement values.

2. In hysteresis mode, the width between the ON point and OFF point becomes the hysteresis width. It cannot be changed with the hysteresis mode setting.

### Window Width Setting




1. Press **SET** when  $uLd$  is displayed, and the window set value set for OUT1 will be displayed.
2. Change the set value using  $\uparrow$  and  $\downarrow$ . The setting range relative to the reference value is 0% to 30% FS.
3. Press **SET** to select the displayed set value, and the window width set value set for OUT2 will be displayed.
4. Change the set value using  $\uparrow$  and  $\downarrow$ .
5. Press **SET** to select the displayed set value, and the system will return to the setting item display ( $uLd$ ).
6. Press  $\uparrow$  and  $\downarrow$  at the same time to return to the setting item display ( $uLd$ ) without changing the selection.

Note: This setting is not valid if hysteresis mode is used.

### Display Refresh Speed Setting

The following refresh speeds can be set.

- 0.1: Displays the average of a 0.1-s interval.
- 0.5: Displays the average of a 0.5-s interval.
- 1.0: Displays the average of a 1.0-s interval.




1. Press **SET** when  $dSP$  is displayed, and the set value set for the display refresh speed will be displayed.
2. Change the set value using  $\uparrow$  and  $\downarrow$ .
3. Press **SET** to select the displayed set value, and the system will return to the setting item display ( $dSP$ ).
4. Press  $\uparrow$  and  $\downarrow$  at the same time to return to the setting item display ( $dSP$ ) without changing the selection.

Note: The number of measurements to average is set with the Measurement Averaging Times Setting (AVE).

### Measurement Averaging Times Setting

Any of the following number of measurement times can be set: 1, 8, 32, or 256.



1. Press **SET** when  $RUE$  is displayed to display the set value set for the measurement averaging times.
2. Change the set value using  $\uparrow$  and  $\downarrow$ .
3. Press **SET** to select the displayed number of times, and the system will return to the setting item display ( $RUE$ ).
4. Press  $\uparrow$  and  $\downarrow$  at the same time to return to the setting item display ( $RUE$ ) without changing the selection.


Note: If the Display Refresh Speed is set to 0.5 s and the Measurement Averaging Times is set to 32, 32 measurements will be averaged as one block and then the block average over 0.5 s will be displayed. This will be repeated every 0.5 s.



### Bar Display Range Setting

The setting range for set values is 1% to 20% FS of the display range per bar.

If the setting is AUT, the best display range will be calculated from the set ON point, and that will be used as the set value.



1. Press  $\text{SET}$  when *bAr* is displayed, and the set value set for the bar display range will be displayed.
2. Change the set value using  $\leftarrow$  and  $\rightarrow$ .
3. Press  $\text{SET}$  to select the displayed set value, and the system will return to the setting item display (*bAr*).
4. Press  $\leftarrow$  and  $\rightarrow$  at the same time to return to the setting item display (*bAr*) without changing the selection.

Note: The bar display function only for output 1. This setting is valid only in Hysteresis Mode.


### Bar Display

The bar display enables intuitively reading the level of the measured pressure relative to the ON point and OFF point. The bar displays data only for OUT1. Also, the display method is different in hysteresis mode and window mode.

#### • Hysteresis Mode

The size of the present measurement value is expressed using five bars with the point between the second and third bars from the left as the ON point.

#### 1-MPa Model, ON Point: 300 kPa



Display range per bar:

$$300 \text{ kPa} \leq 1 \text{ MPa} \times \frac{1}{2}, \text{ so,}$$

$$300 \text{ kPa} \times \frac{1}{3} = 100 \text{ kPa}$$

At condition 1, all three bars on the left will be lit.

The display range per bar will be the set value for the bar display range in the special setting mode. The range will be as follows if the set value is *AUT*.

$$\text{If ON point} \leq \text{Rated pressure} \times \frac{1}{2}:$$

$$\text{Display range per bar} = \text{ON point} \times \frac{1}{3}$$


$$\text{If ON point} > \text{Rated pressure} \times \frac{1}{2}:$$

$$\text{Display range per bar} = (\text{Rated pressure} - \text{ON point}) \times \frac{1}{3}$$

#### • Window Mode

The space between the ON point and the OFF point is divided into five parts, and the position of the present measurement value is expressed using one lit bar. Also, if the measurement value is at or below the ON point or at or above the OFF point, the left and right bars will flash.

#### 1-MPa Mode, ON Point: 300 kPa, OFF Point: 600 kPa



At condition 2, only bar (a) will be lit.

At condition 3, only bar (b) will be lit.

The display range per bar:


$$(\text{Difference between ON point and OFF point}) \times \frac{1}{5}$$

Note: Setting the bar display range for special setting mode is invalid.

### Returning to Measurement Mode

#### Setting items


##### Key protect




##### Hysteresis width




##### Window width



##### Display refresh speed



##### Measurement averaging time



##### Bar LED display range



$\text{SET}$   $\rightarrow$  (to set)

$\leftarrow$  +  $\rightarrow$  (to not set)

Measurement mode

#### To save the set value:

Press  $\text{SET}$  for approx. 2 s when the setting item is displayed.

#### To not save the set value:


Press  $\leftarrow$  and  $\rightarrow$  at the same time when the setting item is displayed.

## Energy-saving Function

The E8F2 has a function to reduce power consumption by displaying the pressure measurement value with the bars only (i.e., turning OFF the digital display).

### Energy-saving 1


Normal measurement mode



1. Press **SET** and **DOWN** at the same time in measurement mode, to turn OFF the digital display.
2. Press **SET** and **DOWN** again at the same time to return to the normal display.


### Energy-saving 2

In window mode, the measurement value (digital display) will flash to signify an alarm if the measurement value is outside the setting range.



1. Press **SET** and **DOWN** at the same time for approx. 3 s to display **ELO**, and after 1 s only the digital display will turn OFF.
2. The digital display will flash along with the bars if the measurement value is at or below the ON point or at or above the OFF point only if the system is set to window mode.
3. Press **SET** and **DOWN** at the same time to return to the normal display.

### Confirmation of ON/OFF Point Set Value



The currently set ON point and OFF point can be checked.

Press  $\odot$  or  $\ominus$  in measurement mode, and  $\bar{0}n$  and ON point set for OUT1 will be displayed alternately.

Press the buttons again to alternately display  $\bar{0}FF$  and the OFF point set for OUT1.

After OUT1 is displayed, press  $\odot$  or  $\ominus$  to proceed to displaying OUT2.

The display will automatically return to the measurement value if there is no key input for approx. 2 s while the set value is displayed.

### Error Display


LED display	Error	Reset method
$E_{r,r}$ (flashing)	Sensor error	Contact OMRON.
$E_{r,s}$ (flashing)	Sensor error	
Pressure value flashing	Input upper limit error	Set the applied pressure to the rated pressure or lower.
	Input lower limit error	Do not apply a reverse pressure. Apply pressure within the rated range.
$E_{r,\bar{0}}$	Output load short-circuit	The load is short-circuited or incorrect wiring is causing overcurrent to flow. Check the wiring and attach an appropriate load if required.
$E_{r,t}$	Teaching input out of range	Perform teaching at pressure within the rated range. If required, change the hysteresis width and window width in special setting mode so that the ON/OFF set values are within the rating.
$E_{r,0}$	Zero reset error	Set the applied pressure to 0 (i.e., atmosphere released).

## Output Impedance

### 1. Measuring the Output Impedance of Voltage Output

#### Models

Figure 1



- Ro : Output impedance
- Rx : Load resistance
- Eo : Output voltage (terminals open)
- Ex : Output voltage (with load Rx connected)
- Ix : Load current (with load Rx connected)

In Figure 1, the current (Ix) that flows when the load resistance (Rx) is connected is calculated as follows:

$$I_x = \frac{E_x}{R_x} = \frac{E_o - E_x}{R_o} \dots\dots(1)$$

The output impedance (Ro) in Equation (1) is calculated as follows:

$$R_o = R_x \left( \frac{E_o - E_x}{E_x} \right) \dots\dots(2)$$

The voltage (Eo) is measured when the output is open, followed by the voltage (Ex) when a load resistance (for example, the minimum value of the permitted load resistance of a transducer) is connected. The measured values Eo and Ex and the connected load resistance (Rx) are inserted into Equation 2 to calculate the output impedance (Ro) of the transducer.

### 2. Measuring the Output Impedance of Current Output

#### Models

In Figure 2, the voltage (Ex) of the output terminals when the load resistance (Rx) is connected is calculated as follows:


$$E_x = I_x R_x = (I_o - I_x) R_o \dots\dots(3)$$

The output impedance in Equation (3) is calculated as follows:

$$R_o = R_x \left( \frac{I_x}{I_o - I_x} \right) \dots\dots(4)$$

Here, the current (Io) is measured with the output short-circuited.

Figure 2



- Ro : Output impedance
- Rx : Load resistance
- Io : Output current (output terminal short-circuited)
- Ix : Output current (with load Rx connected)
- Ex : Output voltage (with load Rx connected)


Next, the output current (Ix) is measured when a load resistance (for example, the maximum value of the permitted load resistance of a transducer) is connected. The measured values Io and Ix and the value of the connected load resistance (Rx) are inserted into Equation 4, and the output impedance (Ro) of the transducer is calculated. The output impedance of the transducer introduced here is the value for normal operation.

### 3. Desirable Output Impedance

In general, it is best to make the output impedance of a voltage output transducer as small as possible, i.e., as close to 0 W as possible, to minimize the effects of load fluctuations on the transducer. For a current output transducer, the opposite is true: the higher the impedance (the closer to infinite impedance), the better.

### 4. Example of Calculation Using Impedance

$$\text{Error in analog voltage output} = \left( 1 - \frac{R_x}{R_o + R_x} \right) \times 100\%$$



Rx	Error
1kΩ	Approximately 10%
10Ω	Approximately 1%

**General Precautions** For precautions on individual products, refer to the *Safety Precautions* in the individual product information.

## **WARNING**

**These products cannot be used in safety devices for presses or other safety devices used to protect human life. These products are designed for use in applications for sensing workpieces and workers that do not affect safety.**



## **Precautions for Safe Use**

### **Withstand Pressure**

Do not apply a pressure higher than the rated withstand pressure. Applying a pressure higher than this may cause damage.

### **Operating Environment**

Do not use the products in an environment where there are explosive or inflammable gases.

### **Power Supply Voltage**

Do not use a voltage that exceeds the power supply voltage range. Using a voltage that exceeds the range may cause burning.

### **Load Short-circuiting**

Do not short-circuit the load. Doing so may cause explosion or burning.

### **Incorrect Wiring**

Be sure that the power supply polarity and other wiring is correct. Incorrect wiring may cause explosion or burning.

## **Precautions for Correct Use**

- When using a Sensor that supports non-corrosive gas as the applicable fluid, use an air filter to remove moisture and oil from the gas.
- Do not insert any wire or other object into the pressure port. Doing so may damage the pressure elements and cause a malfunction.
- Do not use the Sensor alongside high-voltage lines or power lines.
- Mount the Sensor so that it is not subject to ultrasonic vibration.
- Do not apply a tensile force higher than 30 N to the cable or connector.
- The cable can be extended to a maximum of 10 m. For details, see the output impedance section on the previous page.

## Read and Understand This Catalog

Please read and understand this catalog before purchasing the products. Please consult your OMRON representative if you have any questions or comments.

## Warranty and Limitations of Liability

### WARRANTY

OMRON's exclusive warranty is that the products are free from defects in materials and workmanship for a period of one year (or other period if specified) from date of sale by OMRON.

OMRON MAKES NO WARRANTY OR REPRESENTATION, EXPRESS OR IMPLIED, REGARDING NON-INFRINGEMENT, MERCHANTABILITY, OR FITNESS FOR PARTICULAR PURPOSE OF THE PRODUCTS. ANY BUYER OR USER ACKNOWLEDGES THAT THE BUYER OR USER ALONE HAS DETERMINED THAT THE PRODUCTS WILL SUITABLY MEET THE REQUIREMENTS OF THEIR INTENDED USE. OMRON DISCLAIMS ALL OTHER WARRANTIES, EXPRESS OR IMPLIED.

### LIMITATIONS OF LIABILITY

OMRON SHALL NOT BE RESPONSIBLE FOR SPECIAL, INDIRECT, OR CONSEQUENTIAL DAMAGES, LOSS OF PROFITS, OR COMMERCIAL LOSS IN ANY WAY CONNECTED WITH THE PRODUCTS, WHETHER SUCH CLAIM IS BASED ON CONTRACT, WARRANTY, NEGLIGENCE, OR STRICT LIABILITY.

In no event shall responsibility of OMRON for any act exceed the individual price of the product on which liability is asserted.

IN NO EVENT SHALL OMRON BE RESPONSIBLE FOR WARRANTY, REPAIR, OR OTHER CLAIMS REGARDING THE PRODUCTS UNLESS OMRON'S ANALYSIS CONFIRMS THAT THE PRODUCTS WERE PROPERLY HANDLED, STORED, INSTALLED, AND MAINTAINED AND NOT SUBJECT TO CONTAMINATION, ABUSE, MISUSE, OR INAPPROPRIATE MODIFICATION OR REPAIR.

## Application Considerations

### SUITABILITY FOR USE

OMRON shall not be responsible for conformity with any standards, codes, or regulations that apply to the combination of products in the customer's application or use of the product.

At the customer's request, OMRON will provide applicable third party certification documents identifying ratings and limitations of use that apply to the products. This information by itself is not sufficient for a complete determination of the suitability of the products in combination with the end product, machine, system, or other application or use.

The following are some examples of applications for which particular attention must be given. This is not intended to be an exhaustive list of all possible uses of the products, nor is it intended to imply that the uses listed may be suitable for the products:

- Outdoor use, uses involving potential chemical contamination or electrical interference, or conditions or uses not described in this catalog.
- Nuclear energy control systems, combustion systems, railroad systems, aviation systems, medical equipment, amusement machines, vehicles, safety equipment, and installations subject to separate industry or government regulations.
- Systems, machines, and equipment that could present a risk to life or property.

Please know and observe all prohibitions of use applicable to the products.

NEVER USE THE PRODUCTS FOR AN APPLICATION INVOLVING SERIOUS RISK TO LIFE OR PROPERTY WITHOUT ENSURING THAT THE SYSTEM AS A WHOLE HAS BEEN DESIGNED TO ADDRESS THE RISKS, AND THAT THE OMRON PRODUCT IS PROPERLY RATED AND INSTALLED FOR THE INTENDED USE WITHIN THE OVERALL EQUIPMENT OR SYSTEM.

## Disclaimers

### CHANGE IN SPECIFICATIONS

Product specifications and accessories may be changed at any time based on improvements and other reasons.

It is our practice to change model numbers when published ratings or features are changed, or when significant construction changes are made. However, some specifications of the product may be changed without any notice. When in doubt, special model numbers may be assigned to fix or establish key specifications for your application on your request. Please consult with your OMRON representative at any time to confirm actual specifications of purchased product.

### DIMENSIONS AND WEIGHTS

Dimensions and weights are nominal and are not to be used for manufacturing purposes, even when tolerances are shown.

### ERRORS AND OMISSIONS

The information in this catalog has been carefully checked and is believed to be accurate; however, no responsibility is assumed for clerical, typographical, or proofreading errors, or omissions.

### PERFORMANCE DATA

Performance data given in this catalog is provided as a guide for the user in determining suitability and does not constitute a warranty. It may represent the result of OMRON's test conditions, and the users must correlate it to actual application requirements. Actual performance is subject to the OMRON Warranty and Limitations of Liability.

### PROGRAMMABLE PRODUCTS

OMRON shall not be responsible for the user's programming of a programmable product, or any consequence thereof.

### COPYRIGHT AND COPY PERMISSION

This catalog shall not be copied for sales or promotions without permission.

This catalog is protected by copyright and is intended solely for use in conjunction with the product. Please notify us before copying or reproducing this catalog in any manner, for any other purpose. If copying or transmitting this catalog to another, please copy or transmit it in its entirety.