OMRON

スマートセンサ

形 ZX2-LD50V

レーザ変位センサ　CMOSタイプ　センサヘッド

取扱説明書

このたびは、本製品をお買い上げいただきまして、まことにありがとうございます。
ご使用に際しては、次の内容をお守りください。
・電気の知識を有する専門家がお取り扱いください。
・この取扱説明書をよくお読みになり、十分にご理解のうえ、正しくご使用ください。
・この取扱説明書はいつでも参照できるよう大切に保管してください。

オムロン株式会社

© OMRON Corporation 2011 All Rights Reserved.

2175101-9C

安全上のご注意

● 警告表示の意味

⚠ 警告	正しい取扱いをしなければ、この危険のために、軽傷・中程度の傷害を負ったり、万一の場合には重傷や死亡に至る恐れがあります。また、同様に重大な物的損害をもたらす恐れがあります。

● 図記号の意味

	●分解禁止 機器を分解することで、感電などの障害が起こる可能性を示します。

レーザ製品を安全に使用していただくために

レーザ機器に関しては、国内・外でレーザ安全対策が規定されています。国内で使用される場合、国内にて組付けられて海外輸出される場合、これらを3つのケースにわけて説明します。

1.国内で使用する場合
JIS C6802規格で、レーザ製品のクラスに応じて使用者が行わなければならない安全予防対策が規定されています。

● 警告表示

・形ZX2-LD50Vセンサヘッド:クラス1

⚠ 警告

分解しないでください。分解すると、レーザ光がもれ出し視力障害を起こす恐れがあります。

・センサヘッド側面に右図の説明ラベルを貼っています。

2.米国へ輸出する場合
本装置を機器に搭載して米国へ輸出する場合、米国FDA(Food and Drug Administrationの規制)のレーザ規制を受けます。形ZX2-LD50Vは、本規格のLaser Notice NO.50の規定に従いIEC/EN60825-1の基準にてClass1に分類され、CDRH (Center for Devices and Radiologica Health)に届出済みです。
(Accession Number:1020665)
米国へ輸出の際は、説明ラベルを付属品の英文ラベルに貼替えるとともにFDA証明ラベルを右図に示している位置に正しく貼ってください。

・ラベルを貼る位置



3.米国を除く諸外国へ輸出する場合
■形ZX2-LD50Vセンサヘッド
米国以外の地域については、説明ラベルを付属品の英文ラベルに貼替えてください。

■ヨーロッパへの輸出
EN規格によって、本製品はEN60825-1規格に定めるClass1に分類されます。

安全上の要点

以下に示すような項目は安全を確保する上で必要なことですので必ず守ってください。
■設置環境について
・引火性、爆発性ガスの環境では使用しないでください。
・操作や保守の安全を確保するため、高電圧機器や動力機器から離して設置してください。
■電源および配線について
・専用のアンプユニット以外と接続しないでください。
・高圧線、動力線と当製品の配線は別配線としてください。同一配線あるいは同一ダクトにすると誘導を受け、誤動作あるいは破損の原因になることがあります。
・コネクタを着脱するときは、必ず電源を切ってから行ってください。
■設置について
・取付けにおいて、ねじの締め付けは規定のトルク以下で確実に行ってください。
規定のトルク　M3:0.5N・m
■その他
・本体の分解、修理、改造、加圧変形、焼却などは絶対にしないでください。
・廃棄するときは、産業廃棄物として処理してください。
・万が一、異常を感じたときには、すぐに使用を中止し、電源を切った上で、当社支店・営業所までご相談ください。

使用上の注意

製品が動作不能、誤動作、または性能・機器への悪影響を防ぐため、以下のことを守ってください。
■設置場所について
次のような場所には設置しないでください
・周囲温度が定格の範囲を越える場所
・急激な温度変化により、結露が発生する場所
・相対湿度が35～85%RHの範囲を超える場所
・腐食性ガス、可燃性ガスがある場所
・塵埃、塩分、鉄粉がある場所
・振動や衝撃が直接加わる場所
・強い外乱光(レーザ光、アーク溶接光など)があたる場所
・直射日光があたる場所や暖房器具のそば
・水・油・化学薬品の飛沫がある場所
・強磁界、強電界がある場所
■電源および配線について
・アンプユニットは、必ず専用アンプユニット(ZX2-LDA□)をご使用ください。
・センサヘッドからのコード延長は、10m以内としてください。
また、別売の延長ケーブル(ZX2-XC□R)をご使用ください。
■ウォームアップについて
・電源投入後、10分以上経過してからご使用ください。
・電源投入直後は回路が安定していませんので、計測値が徐々に変化することがあります。
■保守点検について
・調整や着脱を行う場合は、必ず電源を切ってから作業をしてください。
・清掃には、シンナー、ベンジン、アセトン、灯油類は使用しないでください。
・センサヘッド前面のフィルタに、大きなゴミやホコリが付いた場合は、ブロアブラシ(カメラレンズ用)で吹き飛ばしてください。呼気で吹き飛ばすことは避けてください。小さなゴミやホコリは柔らかい布(レンズクリーナーなど)にアルコールを少量含ませて、ていねいにふき取ってください。強くふくことは避けてください。フィルタに傷がつくと、誤差の原因になります。
■対象物について
対象物の材質・形状によって、測定できない場合や精度が出ない場合があります。(厚みの薄い透明部材、反射率の極端に小さな材質。スポット径よりも小さな対象物、曲率の大きな対象物、大きく傾斜した対象物など)
■相互干渉について
アンプユニット間に演算ユニット(ZX2-CAL)を接続して使用することにより、複数台のセンサヘッド間の相互干渉を防止できます。ただし、1台のセンサヘッドの受光量が上限値に近い状態のときに別のセンサヘッドのレーザ光が入光すると、その効果を発揮できない場合もあります。相互干渉抑制を目的として演算ユニットを検討される場合は、事前に実機テストで確認してください。

パッケージ内容の確認

・センサヘッド　1台　・フェライトコア　1個　・説明ラベル(和文・英文)　各1枚
・取扱説明書(本書)　1部　・FDA証明ラベル 1枚

1.定格/性能

項目＼形式	形ZX2-LD50V
適用アンプ	ZX2-LDA□
測定中心距離	48mm
測定範囲	±5mm
光源	可視光半導体レーザ(波長660nm、0.24mW以下、JIS クラス1・IEC/EN Class1・FDA Class1)
ビーム径 *1	約φ60μm
分解能 *2	1.5μm
リニアリティ *3	±0.3%F.S.(全範囲)
温度特性 *4	0.06%F.S./℃
周囲温度	動作時:0～50℃　保存時:−15～+70℃(ただし、氷結、結露しないこと)
周囲湿度	動作、保存時:35～85%RH(ただし、結露しないこと)
周囲照度	受光面照度　白熱ランプ:10,000ℓx
耐電圧	AC1000V　50～60Hz　1min.
振動(耐久)	10～150Hz　複振幅0.7mm　X,Y,Z各方向80min.
衝撃(耐久)	300m/s²　6方向各3回(上下、左右、前後)
保護構造	IP67
材質	ケース:ポリブチレンテレフタレート、レンズフィルタ:ガラス、ケーブル:PVC
質量	本体:約75g、梱包状態:約160g

F.S. 測定範囲
(*1)ビーム径:測定範囲の最小径の値(実力値)で、中心光強度の$1/e^2$(13.5%)で定義しています。定義域外に漏れ光があり、対象物の周囲が対象物に比べて反射率が高い場合、誤検出する場合があります。
(*2)分解能:形ZX2-LDAに接続した場合のアナログ出力のゆらぎの幅を示します。(形ZX2-LDAの応答時間を128msに設定し、当社標準対象物(平面ミラー)を中心距離とした場合の測定値を示します。)ワークが静止状態の繰り返し精度を示すもので、距離精度を示すものではありません。強い電磁界内では、分解能の性能が満足できない場合があります。
(*3)リニアリティ:基準ワーク測定時における変位出力の理想直線に対する誤差。
(*4)温度特性:センサと対象物(基準ワーク)の間をアルミの治具で固定した場合の値。(測定中心距離で測定)

2.外形寸法図

(単位：mm)



取りつけ金具

形E39-L178



正反射設置方法

取りつけ金具(形E39-L178)使用の場合



3.センサヘッドの設置について

センサヘッドをM3ねじで固定します。締付けトルクは0.3N・mで確実に取り付けてください。



取り付け穴加工寸法(単位:mm)



重要
・センサヘッドの投光部、受光部には触れないでください。指紋などが付着すると、正しく測定できなくなります。誤って触れた場合は、清潔な柔らかい布で汚れを拭き取ってください。
・コネクタ部は振動や衝撃がかからないように固定してください。

使用者への安全予防対策要求の要約(JIS C 6802:2011規格概要)
※この表は、便宜上要求事項の要約を示したものです。実際の適用については、必ず規格原文をご確認ください。

クラス分類	クラス1
クラスの説明	合理的に予見できる条件下で安全である。
レーザー安全管理者	必要でないが、レーザービームの直接観察を伴うアプリケーションの場合に配置することが推奨される。
リモートインターロック	不要
かぎによる制御	不要
ビーム終端器又は減衰器	不要
放出標識装置	不要
警告標識	不要
ビーム光路	不要
鏡面反射	要求事項なし
目の保護	要求事項なし
防護着衣	要求事項なし
訓練	要求事項なし

4.センサヘッドの接続について

センサヘッドケーブルには、付属品のフェライトコアを必ず取り付けてください。取付位置は、センサヘッド側100mm以内に1個です。



ご使用に際してのご承諾事項

①安全を確保する目的で直接的または間接的に人体を検出する用途に、本製品を使用しないでください。同用途には、当社センサカタログに掲載している安全センサをご使用ください。
②下記用途に使用される場合、当社営業担当者までご相談のうえ仕様書などによりご確認いただくとともに、定格・性能に対し余裕を持った使い方や、万一故障があっても危険を最小にする安全回路などの安全対策を講じてください。
a)屋外の用途、潜在的な化学的汚染あるいは電気的妨害を被る用途またはカタログ、取扱説明書等に記載のない条件や環境での使用
b)原子力制御設備、焼却設備、鉄道・航空・車両設備、医用機械、娯楽機械、安全装置、および行政機関や個別業界の規制に従う設備
c)人命や財産に危険が及びうるシステム・機械・装置
d)ガス、水道、電気の供給システムや24時間連続運転システムなどの高い信頼性が必要な設備
e)その他、上記 a) ～ d) に準ずる、高度な安全性が必要とされる用途
*上記は適合用途の条件の一部です。当社のベスト、総合カタログ・データシート等最新版のカタログ、マニュアルに記載の保証・免責事項の内容をよく読んでご使用ください。

オムロン株式会社　インダストリアルオートメーションビジネスカンパニー

●お問い合わせ先
カスタマサポートセンタ
フリーコール 0120-919-066
携帯電話・PHSなどではご利用いただけませんので、その場合は下記電話番号へおかけください。
電話 055-982-5015 (通話料がかかります)
〔技術のお問い合わせ時間〕
■営業時間:8:00～21:00
■営 業 日:365日
■上記フリーコール以外のセンシング機器の技術窓口:
電話 055-982-5002 (通話料がかかります)
〔営業のお問い合わせ時間〕
■営業時間:9:00～12:00／13:00～17:30 (土・日・祝祭日は休業)
■営 業 日:土・日・祝祭日／春期・夏期・年末年始休暇を除く

●FAXによるお問い合わせは下記をご利用ください。
カスタマサポートセンタ　お客様相談室　FAX 055-982-5051

●その他のお問い合わせ先
納期・価格・修理・サンプル・仕様書は貴社のお取引先、または貴社担当オムロン営業員にご相談ください。

A⓪ 2009年10月

Smart Sensor

OMRON

Model ZX2-LD50V

Laser Displacement Sensor CMOS type
Sensor head unit For Model ZX2-LDA□□

INSTRUCTION SHEET

Thank you for selecting OMRON product. This sheet primarily describes precautions required in installing and operating the product. Before operating the product, read the sheet thoroughly to acquire sufficient knowledge of the product. For your convenience, keep the sheet at your disposal.
Refer to the user's manual for details.

TRACEABILITY INFORMATION:

Representative in EU:
Omron Europe B.V.
Wegalaan 67-69
2132 JD Hoofddorp,
The Netherlands

Manufacturer:
Omron Corporation,
Shiokoji Horikawa, Shimogyo-ku,
Kyoto 600-8530 JAPAN
Ayabe Factory
3-2 Narutani, Nakayama-cho,
Ayabe-shi, Kyoto 623-0105 JAPAN

NOTICE
This is a class A product. In a domestic environment this product maycause radio interference in which case the user may be required to adequate measures.

© OMRON Corporation 2011 All Rights Reserved.

PRECAUTIONS ON SAFETY

●Keys to Warning Symbols

⚠ WARNING	Indicates a potentially hazardous situation which, if not avoided, will result in minor or moderate injury,or may result in serious injury or death. Additionally there may be significant property damage.

●Explanation of signs

	●Resolution prohibition Indicates prohibition when there is a risk of minor injury from electrical shock or other source if the product is disassembled.

●Alert Statements

⚠ WARNING

Do not disassemble the product. Doing so may cause the laser beam to leak,resulting in the danger of visual impairment.

SAFETY PRECAUTIONS FOR USING LASER EQUIPMENT

The ZX2-LD50V use a laser as the light source. Lasers are classified based on EN standard (EN 60825-1)

	ZX2-LD50V
Wavelength	660nm
Peak power	0.24mW max
Classification	Class 1

■Labeling on Laser Use
The ZX2-LD has the following Explanatory label on the side of the sensors.

Using in a country other than U.S.
・For countries other than Japan and U.S., Explanatory labels must be replaced by English ones (supplied with the product). EN60825-1 is provided for products used in Europe, and the content of this standard differs.
・The ZX2-LD50V is categorized as a Class 1 device as stipulated in EN60825-1:2007.
When using devices in which ZX2-LD50V is installed in the U.S., the devices are subjected to the U.S. FDA (Food and Drug Administration) laser regulations. ZX2-LD50V is classified into Class 1 by the standard of IEC/EN60825-1 according to deviations of Laser Notice NO.50 of this standard, and reported to CDRH (Center for Devices and Radiological Health).
(Accession Number : 1020665)
Put the FDA Certification label. (supplied with the sensor)
Please make sure that the label are affixed at the correct locations as indicated.



PRECAUTIONS FOR SAFE USE

Please observe the following precautions for safe use of the products.
(1)Installation Environment
・Do not use the product in environments where it can be exposed to inflammable/explosive gas.
・To secure the safety of operation and maintenance, do not install the product close to high-voltage devices and power devices.
(2)Power Supply and Wiring
・Use only products that have been made expressly for the Controller
・High-Voltage lines and power lines must be wired separately from this product. Wiring them together or placing them in the same duct may cause induction, resulting in malfunction or damage.
・Always turn off the power of the unit before connecting or disconnecting cables.
(3)Installation
・Make sure to tighten all installation screws securely.(tightening torque: M3, 0.5N・m)
(4)Other Rules
・Do not attempt to disassemble, deform by pressure, incinerate, repair, or modify this product.
・When disposing of the product, treat as industrial waste.
・If you notice an abnormal condition such as a strange odor, extreme heating of the unit, or smoke, immediately stop using the product, turn off the power, and consult your dealer.

PRECAUTIONS FOR CORRECT USE

Please observe the following precautions to prevent failure to operate, malfunctions, or undesirable effects on product performance.
(1)Do not install the product in locations subjected to the following conditions:
・Surrounding air temperature outside the rating
・Rapid temperature fluctuations (causing condensation)
・Relative humidity outside the range of 35 to 85%
・Presence of corrosive or flammable gases
・Presence of dust, salt, or iron particles
・Direct vibration or shock
・Reflection of intense light (such as other laser beams, electric arc-welding machines, or ultra-violet light)
・Direct sunlight or near heaters
・Water, oil, or chemical fumes or spray, or mist atmospheres
・Strong magnetic or electric field
(2)Power Supply and Wiring
・Use only products that have been made expressly for the Controller
・To extend the cable from the sensor head, an optional extension cable(ZX2-XC□R) must be used.
(3)Warming Up
・After turning on the power supply, allow the Controller to stand for at least 10 minutes before use. The circuits are unstable immediately after the power supply is turned on and attempting measurement may result in inconsistent measurement values.
(4)Maintenance and inspection
・Always turn off the power of the unit before connecting or disconnecting cables.
・Do not use thinner, alcohol, benzene, acetone, or kerosene to clean the sensor.
・If considerable foreign matter or dust collects on the front of sensor, use a blower brush (for camera lenses) to blow off the foreign matter. Avoid blowing it off with your breath. For a small amount of foreign matter or dust, gently wipe with a soft cloth. Do not wipe hard. If the surface is damaged, false detection may result.
(5)Sensing Object For Reflective Type Sensor Head
・The product cannot accurately measure the following types of objects: Thin and transparent objects, objects with an extremely low reflective sensor ratio, objects smaller than the spot diameter, objects with a large curvature, excessively inclined objects,etc.
(6)Mutual interference
・Inserting a calculation unit between amplifier units can prevent mutual interference between sensor heads. However, this may not work efficiently if Amount of light received of one sensor head is saturated because of the luster of work-pieces and a laser beam of the other sensor head is input. If you are interested in installing a calculation unit in order to prevent mutual interference, carry out a test using the actual system beforehand.

Checking the package contents

・Sensor head ×1 ・Ferrite core ×1 ・Laser Explanatory label ×1 ・Manual (this paper) ×1
・FDA Certification label ×1

1.Specifications

Item \ Model	ZX2-LD50V
Applicable Amplifier Units	ZX2-LDA□
Measuring center distance	48mm
Measuring range	±5mm
Light source	Red semiconductor laser (λ=660nm, 0.24mW max., IEC/EN Class1・FDA Class1)
Beam diameter (*1)	Approx.60um-dia.
Resolution (*2)	1.5μm
Linearity (*3)	±0.3%F.S. (Full range)
Temperature characteristic (*4)	0.06%F.S./℃
Surrounding air temperature	Operating: 0 to 50℃, Storage: −15 to 70℃ (with no icing or condensation)
Ambient humidity	Operating and storage: 35% to 85% (with no condensation)
Operating ambient illumination	Illuminance on receiving optical side 10,000 lx (incandescent light)
Dialectic strength	1,000 VAC, 50/60 Hz for 1 min
Vibration resistance (destructive)	10 to 150 Hz, 0.7-mm double amplitude, 80 min each in X, Y, and Z directions
Shock resistance (destructive)	300 m/s² 3 times each in six directions (up/down, left/right, forward/backward)
Degree of protection	IP67
Materials	PBT (Case), Glass (Lensfilter), PVC(Cable)
Weight (packed state)	Approx.160g (sensor head: Approx. 75g)

F.S.: Full scale of measurement
(*1)Beam diameter: Value of minimum diameter in measuring range. The typical value at the measuring center distance is shown. Defined as $1/e^2$ (13.5%) of the center intensity. The beam diameter may sometimes be affected by the ambient condition of the object such as leaked light fromthe main beam.
(*2)Resolution: Fluctuation width of linear outputs when connected to Amplifier Unit (With response time set to 128ms and the standard work (flat mirror) placed at the measuring center distance) This value is repetition accuracy of the static condition work, and not distance accuracy. In a strong electromagnetic field, the performance of resolution might not be able to be satisfied.
(*3)Linearity: The error in relation to the ideal displacement output straight line when the standard work ismeasured
(*4)Temperature characteristic: Value obtained when the sensor and object (standard work) are fixed with an aluminum jig. (Measured at the measuring center distance)

4.Dimensions

(UNIT:mm)



Mounting Bracket
E39-L178



Installation for specular reflection model
Using mounting bracket E39-L178





*1 The measurement distance reference position is the end face of the mounting bracket.
*2 To make fine adjustment for the specular reflection type, secure the main unit rotated in the counterclockwise direction.

Note. When attaching the unit to the mounting bracket, insert a screw from the Explanatory label side.

2.Installing Sensor Heads

Fix the Reflective type sensor head with screws (M3). (tightening torque: M3, 0.3N・m)



Mounting hole dimensions (Unit:mm)



CHECK!
When mounting a Sensor Head, take care not to touch the emitter and receiver. Adhesion of finger marks may hinder correct measurements. If you have touched them, wipe them with a clean soft cloth.

Summary of manufacturer's requirements (EN60825-1:2007)

Classification	Class 1
Description of hazard class	Safe under reasonably foreseeable conditions
Laser Safety Manager	Not required but recommended when using an application with direct observation of laser beam.
Remote interlock	Not required
Key control	Not required
Beam terminator or attenuator	Not required
Emission warning device	Not required
Warning	Not required
Beam path	Not required
Mirror reflection	No requirement
Eye protection	No requirement
Protective clothing	No requirement
Training	No requirement

3.Sensor connections

A ferrite core (supplied with the sensor head) must be attached to the sensor cable. The ferrite cores can be connected within 100 mm from the sensor.



Suitability for Use

THE PRODUCTS CONTAINED IN THIS SHEET ARE NOT SAFETY RATED. THEY ARE NOT DESIGNED OR RATED FOR ENSURING SAFETY OF PERSONS, AND SHOULD NOT BE RELIED UPON AS A SAFETY COMPONENT OR PROTECTIVE DEVICE FOR SUCH PURPOSES.
Please refer to separate catalogs for OMRON's safety rated products.

OMRON shall not be responsible for conformity with any standards, codes, or regulations that apply to the combination of the products in the customer's application or use of the product.

Take all necessary steps to determine the suitability of the product for the systems, machines, and equipment with which it will be used.
Know and observe all prohibitions of use applicable to this product.

NEVER USE THE PRODUCTS FOR AN APPLICATION INVOLVING SERIOUS RISK TO LIFE OR PROPERTY WITHOUT ENSURING THAT THE SYSTEM AS A WHOLE HAS BEEN DESIGNED TO ADDRESS THE RISKS, AND THAT THE OMRON PRODUCT IS PROPERLY RATED AND INSTALLED FOR THE INTENDED USE WITHIN THE OVERALL EQUIPMENT OR SYSTEM.
See also Product catalog for Warranty and Limitation of Liability.

■ EUROPE
OMRON EUROPE B.V. Sensor Business Unit
Carl-Benz Str.4, D-71154 Nufringen Germany
Phone:49-7032-811-0 Fax: 49-7032-811-199
■ NORTH AMERICA
OMRON ELECTRONICS LLC
One Commerce Drive Schaumburg,IL 60173-5302 U.S.A.
Phone:1-847-843-7900 Fax : 1-847-843-7787
■ ASIA-PACIFIC
OMRON ASIA PACIFIC PTE. LTD.
No. 438A Alexandra Road #05-05-08(Lobby 2),
Alexandra Technopark, Singapore 119967
Phone : 65-6835-3011 Fax :65-6835-2711
■ CHINA
OMRON(CHINA) CO., LTD.
Room 2211, Bank of China Tower,
200 Yin Cheng Zhong Road,
PuDong New Area, Shanghai, 200120, China
Phone : 86-21-5037-2222 Fax :86-21-5037-2200

OMRON Corporation

D ⓪ OCT, 2009