

## UN300 – Ultrasonic Sensor with LED Display



- ▶ 4-digit LEDs display, all-metal housing
- ▶ Rotatable indicator, PNP/NPN programmable
- ▶ 4..20mA/0...20mA/1...5V/0...5V output programmable
- ▶ Liquid level / distance measuring mode programmable
- ▶ Narrow-beam, applicable to liquid and solids
- ▶ Optional intrinsically safe model

UN300 contains an ultrasonic transmitter and an electronic module, the transmitter transmits ultrasonic pulses towards the level surface. The period during individual pulses spread towards the level and back was obtained and subsequently converted by the electronic module to an output current 4 – 20 mA or voltage 0 – 10V. All-metal housing, rotatable highlight LED display, dual keys design, user friendly menu, 330° rotatable indicator.

## Specifications


<b>Measuring Range</b>	0.06...0.5m/0.10...0.80m/0.20...2.00m/0.30...3.50m
<b>Applicable Medium</b>	Solids or liquid
<b>Beamwidth</b>	7°
<b>Response Time</b>	For details please see 'technical data'
<b>Accuracy</b>	≤0.2% of F.S. or ±2mm
<b>Power Supply</b>	12...30Vdc
<b>Current Consumption</b>	≤40mA (power supply 24Vdc, no-load)
<b>Switching Output</b>	
Output	Push-pull (compatible with PNP / NPN); NC / NO configurable
S1, S2 Output Current	<500mA
Voltage Drop	<1V
<b>Current Analog Output</b>	
Output	3-wire 0...20mA / 4...20mA programmable
Load RA	RA≤0.5KΩ
<b>Voltage Analog Output</b>	
Output	3-wire 0...5V / 1...5V programmable
Load RA	RA>10KΩ
<b>Linearity</b>	≤±0.2% of F.S.
<b>Wiring Protection</b>	Reverse polarity, overvoltage and short-circuit
<b>Display</b>	
Design/Display Range	8mm height, red 4-digit LED / -1999...9999
<b>Temperature</b>	
Operating/Storage	-20...+85°C
<b>Material</b>	
Display Head	Zinc Alloy
Housing/Sensor	316 stainless steel/epoxy resin, POM
<b>Protection Class</b>	IP67
<b>Electrical Connection</b>	M12×1 plug

## Applications

- ▶ Food & pharmaceutical industry
- ▶ Power plant
- ▶ Plastics processing
- ▶ Papermaking
- ▶ Water treatment

## Technical Data

Measuring Range(m)	0.06...0.50	0.10...0.80	0.20...2.00	0.30...3.50
Response Time(ms)	100	100	250	400
Resolution(mm)	0.5	0.8	1	1
Dead Zone(mm)	60	100	200	300

Set panel

- 1 – LOGO  
2 – 8 state lights  
3 – 4-digit LED display window  
4 – Keys

<b>S</b> + <b>E</b>	Press and hold for 2 seconds to enter setting mode/verification
<b>S</b>	Shift down the menu / change values
<b>E</b>	Shift up the menu / change setting position

## Menu

Display	Item	Description	Options
<i>unit</i>	unit	unit	cm/inch
<i>SP1</i>	SP1	set point of output 1	2% ...100% of F.S.
<i>rP1</i>	rP1	reset point of output 1	lower limit ... 98% of F.S.
<i>out1</i>	out1	output mode	hysteresisNC/NO window NC/NO
<i>SP2</i>	SP2	set point of output 2	2% ...100% of F.S.
<i>rP2</i>	rP2	reset point of output 2	lower limit ...98% of F.S.
<i>out2</i>	out2	output mode	hysteresisNC/NO window NC/NO
<i>SFun</i>	sfun	output function	PNP / NPN

Display	Item	Description	Options
<i>Aout</i>		current analog output	0...20mA or 4...20mA
		voltage analog output	0...5V or 1...5V
<i>ASet</i>	Ast	analog output start point	lower limit ...75% of F.S.
<i>AEnd</i>	AEd	analog output end point	25%...100% of F.S.
<i>Mode</i>	Mode	operating mode	distance or level measuring
<i>Save</i>	Sto	save	Yes/No



## Functional specifications

## Hysteresis Mode


The hysteresis keeps the switching output stable if the measured value fluctuates around the setpoint. Output switches when rising measured value reaches set point (SP1); As measured value falls, the output switches back only if the reset point (rP1) is reached.

## Window Mode

The window function allows the monitoring of a defined range. If the measured value is between set point (SP1) and reset point (rP1), the output is activated(NO), otherwise it is deactivated(NC).




## Working Mode



L : distance from sensor to objective surface

DV : display value

**Distance measuring mode :** The further distance between sensor and objective surface, the larger value displayed, and vice versa.





L : distance from sensor to objective surface

DV : display value


**Level measuring mode :** The less distance between sensor and objective surface, the larger value displayed, and vice versa.

## Wiring

Signal	Plug	Cable
U+	1	Brown
U-	3	Blue
Switching output S1	4	Black
Switching output S2	2	White
Analog output (Current or Voltage)	5	Gray



## Dimensions in inches (mm)



## Order Code

UN :	Ultrasonic sensor with digital display
300 :	Series#
20 :	2 switching outputs
21 :	2 switching outputs + 1 analog (0...20/4...20mA) output
22 :	2 switching outputs + 1 analog (0...5/1...5V) output
F :	Flange connection
G :	G1-1/2 male thread
N :	1-1/2" NPT male thread

UN	300/	21/	F	S	M0.5	/
----	------	-----	---	---	------	---

S : M12X1 5-pin plug

C : Cable outlet

MXXX : The upper limit of measuring range(metric system) xxx m

IXXX : The upper limit of measuring range(english system) xxx inch

Note: M0.5 means that the measuring range is 0.06...0.5m.

Others

## Sepecial Order on Request

- ▶ Electrical and / or process connection